BCO10331687 Residential final Inspection Inspection checklist outcome statement 05-10-2021 5/16 Tawhiri Road One Tree Hill Auckland 1061



should an hearther behavior

Important Note: The following inspection checklist must be read in conjunction with the Auckland Council Inspection Code of Practice where individual line items have been defined to support reasons for decisions. N/A means Not Applicable (not part of this inspection)

* Indicates a photo has been taken in relation to a particular line item.

ment. Pletenes

	City sieness
Inspection Details	
Inspection Type Code	Residential final(IF1)
Date of inspection	05-10-2021
Building name	N/A
Floor/Units (Multi Unit only)	N/A
Lot	N/A
Start time	07:00:55
Scope	Recheck
Partial description mandatory	N/A
Does the checklist need to be completed?	No
Inspection to be completed under supervision	No
Supervision level	N/A
Site safety	Safe
Unsafe site	N/A
Comment - Site Safety (Near Miss)	N/A
Consent documents on site	Yes
Previous inspection history checked	Yes
Involves restricted building work	Yes
LBP information	Provided

Checklist Item	Result	Comment

LBP Name (if applicable)	LBP Number	LBP Class
Jinshun Zheng	130749	LBP Carpentry

Documents required	Comment
Not applicable to this inspection.	

Minor Variation Description (if applicable)	Outcome	Outcome reason / Comment
Not applicable to this inspection.		

Inspection Summary	
Fail Comments	Not applicable to this inspection.
	SCOPE: RBW - Alterations to existing bathroom and laundry. Add new ensuite. Move kitchen and create new bedroom. Add gas water heater.
	NOTES FROM PREVIOUS INSPECTION:
	1/10/2021: Met with Alex on site & reviewed plans. Checked layout - as per plan. Internal linings plastered & painted, bathrooms tiled/painted, kitchen & laundry completed. Floor coverings laid. Synthetic 'Boat' type carpet laid in Garage. Carried out inspection using itemized checklist on tablet. Smoke alarms installed and working. Work has generally been completed to a good standard. Generally OK, however some minor items require remedial work.REMEDIALS:
Additional Comments	=======================================
	5/10/2021 :

	Met with Alex & reviewed Remedial items. 1) Shower panels in bathroom & En-suite now sealed. 2) Window restrictors now fitted. 3) PVC vermin discs under cabinets now sealed in place. OUTSTANDING: PS3 for pressure test to be provided. Viewed on site.
Inspection Outcome	Pass
Work completed in accordance with plans	Yes
Work completed in accordance with plans	N/A
Comment - other	N/A
Person on site (name)	Alex.
Inspection outcome statement recipient email	nziflooring@gmail.com
Inspector's name	Matthew Greenhough
Inspector's email	MATTHEW.GREENHOUGH@AUCKLANDCOUNCIL.GOVT.NZ
Inspectors phone number	+64 21 897 128
Inspection duration (minutes) Note- Time may be added for travel and additional processing (eg minor variations)	40
Supervisor's name	N/A
Supervisor's email	N/A
Supervision outcome	N/A
Next inspection required	No inspection apply for CCC

Photos	
--------	--

BCO10331687 IF1 Inspection 05/10/2021

BCO10331687 IF1 Inspection 05/10/2021

LPB details,

BCO10331687 IF1 Inspection 05/10/2021

BCO10331687 IF1 Inspection 05/10/2021

BCO10331687 IF1 Inspection 05/10/2021

BCO10331687 IF1 Inspection 05/10/2021