



# **13A Healthy Homes Statement**

Page 1 is a compliance statement to be signed by Landlord	Landlord shall print this page and include with any new, renew or updated tenancy contract hereon.
ADDRESS OF TENANCY:	24 Springwood Place, Mt Eden
GENERAL EXEMPTION	In some situations this tenancy may be exempt from complying with all or parts of the healthy homes standards. Please cross out if any of the following 2 DO NOT apply.
1.	The tenant is the immediate former owner of the property and the tenancy started immediately after the landlord acquired the property from the tenant. This exemption will only apply for 12 months from the tenancy start date.
2.	The landlord intends to demolish or substantially rebuild the rental property and has applied for or has been granted the relevant resource or building consent. This exemption will last for up to 12 months from the healthy homes compliance date. This exemption will cease if the application for consent is refused (unless challenged) or the consent(s) lapses or is terminated. This exemption will cease to apply if you receive a request to provide evidence that you have applied for the relevant consent(s) and this evidence is not provided within 10 working days (or a time period provided in a Tenancy Tribunal order).
DRAINGAGE AND MOISTURE INGRESS	For more information on all aspects of the moisture ingress and drainage standard, including a comprehensive guidance document, visit https://www.tenancy.govt.nz/healthy-homes/moisture-and-drainage-standard/
Does the property have gutters and downpipes that efficiently drain storm water, surface water, and ground water to an appropriate outfall? An appropriate outfall will generally be the storm water system provided by your local council. It could also be a properly working soakage system, natural watercourse, adequate water storage system or other constructed water way.	YES
Landlords:	Must still take all reasonable steps to ensure the rental property or building complies with the healthy homes standards to the greatest extent reasonably practicable.
Landlords:	Must still take all reasonable steps to ensure the rental property or building complies with the healthy homes standards to the greatest extent reasonably practicable.
Does the property have any enclosed subfloor spaces?	NO
Landlord intent:	To install ground moisture barrier in order to comply with the Healthy Homes Standard: It was never installed becasue it was never an requirement before.
INSULATION STANDARD	For more information on all aspects of the insulation standard, including a comprehensive guidance document, visit https://www.tenancy.govt.nz/healthy-homes/insulation-standard
CEILING INSULATION	Ceiling insulation is required in all areas of the premises, unless these are areas: > that are not a domestic living space > of the ceiling that have a domestic living space directly above
Does the CEILING insulation above all domestic living spaces meet the requirements of the insulation standard?	YES - Entire Premises



Can we identify the R-Value in the ceiling?	NO
Ceiling Insulation thickness (mm) when last inspected:	280
Can we confirm ceiling Insulation installed date?	Unknown
Date insulation was inspected:	06/08/2020
Type of ceiling insulation:	Segment
We confirm the insulation is in reasonable condition (without any mould, dampness, damage or gaps)	YES
This exemption applies:	Because the current insulation does not need to meet the R-value required under the healthy homes insulation standard. This exemption applies because: a) there is ceiling insulation that covers the ceiling at the premises; and b) the insulation was installed before 1 July 2016; and c) immediately before the healthy homes compliance date, the landlord met the insulation requirements already in force ; and d) the minimum thickness of the insulation material is at least 120 mm
Landlord confirms	That all reasonable steps will be taken to find this information.
Does the property meet the partial exemption for certain thermal underfloor insulation?	NO
This partial exemption applies because:	a) there is underfloor insulation; and b)when the insulation was installed, there were requirements relating to thermal insulation that applied to the premises (under an enactment or bylaw); and c) the landlord has a compliance document showing that when the insulation was installed, the premises met these requirements.
Does the UNDERFLOOR insulation meet the requirements of the insulation standard?	NO - Non of the premises
The R-value:	Should be stated in the current statement of insulation or may be included in the council building file. Landlords need to check all possible sources and include finding with this statement.
The R-value:	Should be stated in the current statement of insulation or may be included in the council building file. Landlords need to check all possible sources and include finding with this statement.
The reason(s) why the underfloor area isn't insulated:	Concrete floor unable to install
Can we determine any existing Insulation may existed?	NO
Landlord will:	attempt to obtain Insulation information in council building file. Landlord will be attached the finding to this statement. The underfloor space is also not possible for a professional assessor to gain access and provide an assessment. The landlord confirms that all reasonable steps will or have been taken to find this information.
WALL INSULATION	Wall insulation is not compulsory in rental property. Assessor do not know if there is any wall insulation. Landlord must include a copy of such information to this statement if they known. Landlord must take all reasonable steps to find the information.
HEATING STANDARD	For more information on all aspects of the heating standard, including a comprehensive guidance document, visit https://www.tenancy.govt.nz/healthy-homes/heating-standard



Heating Exemption:	NO heating exemption applies
Currently:	This house have a certification as a passive house under the passive house standard of the Passivhaus Institut, Germany or A current living building certification or A current Petal certification (which includes a heating requirement or A current Zero Energy certification.
The required heating capacity (kW):	5.1
Type of qualified Heater:	Heat Pump
Qualified heater's heating capacity (kW):	4
Does the 'tolerance' or 'top up' allowance for existing heaters apply?	YES
The heating condition means:	Additional fixed Electrical heater (not heat pump) Max1.5kW is required for top up purpose
VENTILATION STANDARD	For more information on all aspects of the ventilation standard, including a comprehensive guidance document, visit https://www.tenancy.govt.nz/healthy-homes/ventilation-standard
Does each room in the rental property with an indoor cooktop, bath or shower have an extractor fan installed that vents to the outside and is in good working order?	YES - All rooms
What is the diameter or exhaust capacity of each extractor fan?	All fans were installed before 1 July 2019 don't need to meet performance requirements of the ventilation standard. In this case, we are relying on the modified standard for extractor fans installed before this date.
Landlord	Intend to install/repair these extractor fans connected externally.
Landlord	Intend to install/repair these extractor fans connected externally.
Do all habitable rooms in the property have one or more windows, doors or skylights that open to the outside and meet the requirements?	YES - All habitable spaces
Landlord intend to fix the shortage to exceed the 5% requirement.	Intend to fix the shortage to exceed the 5% requirement.
A room does not need to meet the requirements for openable windows and external doors if it was lawful at the time it was built or converted into a habitable space. If having fewer windows or doors was only lawful because the room met alternative ventilation requirements:	Then those requirements must still be met to qualify for this exemption.
DRAUGHT STOPPING STANDARD	For more information on all aspects of the draught stopping standard, including a comprehensive guidance document, visit https://www.tenancy.govt.nz/healthy-homes/draught/
Does this property have any open fireplaces?	NO



Is the property free from unintentional and unreasonable gaps or holes that allow noticeable draughts in or out of the building? Areas include, but are not limited to, doors, windows, walls, floors and ceilings.	NO, we have observed either gaps is great than 3mm and/or broken/loose hinges/catches that prevent closing tightly and/or obstruction that prevent closing tightly and/or unable to close the windows or door.
Statement:	Landlord intent to remedial all the defects identified in the statement in order to comply with the Healthy Homes Standard. Once work is complete, landlord or the company that engaged doing the work will attach a copy of the invoice/letter with this statement to supersede to non compliance.Landlord will ensure this rental property comply with healthy homes standards within 90 days of any new, or renewed, tenancy from 1st July 2021 and before 1st July 2024.
I/We [Name of landlord(s)],	declare that the information contained in this statement is true and correct as at the date of signing.
Sign By:	
Date Signed:	

### **General Information**

Location / GPS		Dexter Ave
	Tenterden Ave	
		Paddington Green
	Balmoral Rd	
	Eat: -36.887079 Long: 174.7516531	© Mapbox, © OpenStReamMap,



External photo	
Date of Assessment	06/08/2020
Customer Name	DVS property investment Ltd
Assessor's Name	Daniel Roan
Weather Condition	Fine
Season	Winter


### DRAINAGE & MOISTURE

Subsections	1. Spouting 2. Downpipe 3. Ground Surface Water
	4. Moisture

### Drainage - Spouting

Spouting Result:	PASS
Recommendation:	Appropriate gutters to remove water from the roof
Spouting Photos:	






# Drainage - Downpipe

Downpipe Result:

PASS






Drainage - Ground Surface Water



Ground Surface Result:	PASS
Recommendation:	Efficiently drain storm water, surface water and ground water to an appropriate outfall.
Surface ground Photos	<image/>





# Drainage - Subfloor Moisture

Subfloor Result:

EXEMPT



Reason for Exemption:	Concrete floor
Subfloor Photos:	

### INSULATION

Please see the following 2 Subsections	1. Underfloor 2. Ceiling
Insulation - Underfloor	
Underfloor Insulation Result:	EXEMPT
Reason for exemption:	Concrete Base




U/F Insulation Condition Photos:



# **Insulation - Ceiling**

Ceiling Insulation Result:	PASS
Recommandation:	Installed as per NZS4246 and the HHS requirements.
Type of Existing Insulation:	Polyester
Colour of the Existing Insulation:	Green





### **HEATING**

Areas included in output calculation:

Lounge, Kitchen, Dinning



Recommendation:	Remedial work is required. Please seek a professional company that specialist in this area to look at the issue(s) we observed. New heat source output kW must be equal or greater then required.
Is the existing approved heat source producing heat?	No
We have observed:	Existing heat source isnt working
Recommend installing the following approved heating source:	Fixed Electrical heater (not heat pump) Max1.5kW for top up purpose, Heat Pump (most energy efficient way to heat a house)
Additional comments:	Remote disnt work, used tenant mobile app to activate but no heat is coming out.
Heating Photos:	<image/>





### VENTILATION

Please see the following 3 subsections for details:

- 1. Kitchen(s) 2. Bathroom(s) 3. Windows
- Ventilation Kitchen(s)

KITCHEN(s) Ventilation Result:	PASS
Recommendation:	Existing Extraction method is sufficient and approved under HHS standard.
Is the approved extraction system currently working?	Yes




Kitchen External Photo:	
Kitchen Internal Photo:	

# Ventilation - Bathroom(s)

Recommendation:	Existing Extraction method is sufficient and approved under HHS standard.
Bathroom 1 Ventilation Result:	PASS
Is the extraction fan currently working?	Yes







Bath 1 Internal Photo: **Ventilation - Windows** 

Rooms for Ventilation Calculation	Open Plan, Master Bedroom, Bedroom 3, Bedroom 2
Recommendation:	Existing operable windows are sufficient and approved under HHS standard.
Condition of PASS:	In each room, the size of the openable fixed windows, doors and skylights together must be at least 5% of the floor area of that room



Typical Fixed Openable Window photo:



Open Plan Ratio (%):	10.4
Open Plan result:	PASS
Open Plan (includes):	Lounge, Kitchen, Dinning
Bedroom 1 (Master) Ratio (%):	11.0
Bedroom 1 (Master) result:	PASS
Bedroom 1 Location:	End of hallway
Bedroom 2 Ratio (%):	12.4
Bedroom 2 result:	PASS
Bedroom 2 Location:	Next to bedroom 1
Bedroom 3 Ratio (%):	24.0
Bedroom 3 result:	PASS
Bedroom 3 Location:	Next to toilet

### DRAUGHT

Recommendation:	Remedial work is required. Please seek a professional company that specialist in this area to look at the issue(s) we observed.
Observed Open Fireplace(s):	No
We observed gap(s) is more then 3mm in some area	Observation is from the inside of the house. It is possible the actual gap maybe less then 3mm between the frame and window/door. Further proof is required by an professional company.



PLEASE NOTE:	All the location of the open plan and room numbers listed below follow the Ventilation Sector's location description.
Draught - Open Plan	
Result:	PASS
Draught - Entrance Foy	er
Result:	PASS
Draught - Laundry Roor	n
Result:	FAIL
Failure in:	External Door
Failure reason:	Gaps is great than 3mm
Photos:	

# Draught - Bathroom 1 (Master)

Result:	FAIL
Failure in:	Window
Failure reason:	Gaps is great than 3mm



# Photos:

# Draught - Toilet 1

Result:	PASS	
Location:	Downstair	
Draught - Toilet 2		
Result:	PASS	
Location:	Upstairs	
Draught - Bedroom 1 (Master)		
Result:	PASS	
Draught - Bedroom 2		
Result:	PASS	
Draught - Bedroom 3		
Result:	PASS	
Disclaimer		



Please read	This report is based on our observations and measurements on the day of our site assessment. The assessment is limited to a visual inspection only of the sections required by the Tenancy Service, which the Inspector has reasonable access to and which is in their clear unobstructed line of sight. We also may not know if the landlord own the entire building if we assess individual units. Where we exempted due to owner do not own the whole building but was not disclose to Cosy Spaces NZ. Cosy Spaces NZ do not hold responsibility of the accuracy of the report. Excluded from inspection are any areas of the premises, which cannot be visually inspected due to concealment or obstructions. Any changes to the site after our visit may affect this report. Please review this report carefully. Where we have offered recommendations or indicated a non-compliance we will provide a quote for services which Cosy Spaces NZ are able to undertake. Any suggestion or recommendations contained in the Report are suggestions only and it shall be the responsibility of the person or persons carrying out the work to ensure the most appropriate remedy is carried out in conjunction with any further discoveries, warranty's, and any necessary local authority consents obtained prior to proceeding with remedial work. Landlord/Property Manager confirms that the following general exemption rules do not apply to this property. If it does, this report only becomes valid from the date of the expiration of the exemption period: 1. If the landlord intends to demolish or substantially rebuild the rental property and has applied for the relevant resource or building consent before the healthy homes compliance date. It may end earlier in certain circumstances, for example, if the consent lapses or is terminated, or the application for consent is refused. If requested, the landlord will need to provide evidence that they have applied for the relevant resource or building consent. 2. If the tenant is the immediate former owner of the rental property and the